

Proprietary Tensioned Cable System:

Results of a Three Year In Service
Evaluation

Ohio Department of Transportation

District 8

E. Thomas Arnold, Jr., E.I.

Introduction

- Existing Conditions
- Cable Barrier Installation
- 3-Year ISPE
- Crash Trends
- Notable Crash Types
- Conclusion

Existing Conditions

Existing Conditions


- IR-75 from SR-129 to SR-73 in Butler and Warren Counties
- Urban Interstate
- 3 lanes in each direction




Existing Conditions

- 22% Trucks throughout this time frame

Average Daily Traffic



Median Characteristics



Cross-Over Crash Experience

- 11 fatal cross-over crashes occurred from October 2000 through December 2001
- No common contributing factors identified

Low Cost/Short Term Countermeasures

- Increased State Highway Patrol presence
- Installed rumble strips

**Crashes Reduced
until OSP Presence
Relaxed**

Cable Barrier Installation

Brifen Installation

■ Concrete Barrier	\$4,500,000
■ Mounding	\$2,800,000
■ Barrier Guardrail	\$1,200,000
■ Cable Barrier	\$1,045,000


System Description

- 14.5 miles of wire rope installed on IR-75 in Butler and Warren Counties
- Cost: \$1,045,000 (2001 dollars)



System Description

- Approx. 85% (12.5 miles) driven posts and 15% (2 miles) socketed posts
- 4 pre-tensioned wire ropes woven around posts
- Posts spaced at approx. 10'



System Description

- The wire rope is located approximately 14' from the edge line



3-Year In-Service Performance Evaluation

ISPE

- FHWA Approved
 - Used in over 30 Countries
 - 2nd installation in US
 - 1st in Ohio
- ODOT was required to perform a 3-year ISPE

ISPE



**TENSIONED CABLE GUARDRAIL
ACCIDENT REPORT AND EVALUATION FORM**
Ohio Department of Transportation

CRASH LOCATION

County: BUTLER Route: IR-75 Milepost: 24.1 Direction: NORTHBOUND
Horizontal curve: Tangent Length: ft. Direction: n/a

COLLISION DATA (Sketch accident on reverse side or attach separately)

Date of Accident: 4/13/06 Day of Week: Thursday Time: 10:59pm
Weather: Clear/Cloudy and Dry
Estimated Angle of Impact: 15 degrees
Estimated Speed at Impact: 65 mph
Result of collision: Stopped in Contact
Describe sequence of events leading to accident: Unit 1 made an improper lane change, sideswiped a truck, lost control, and struck the wire rope

VEHICLE AND OCCUPANT

Vehicle Type: Car Vehicle Make: Honda Model: Prelude Year: 1986
Describe Damage to Vehicle: Disabling damage to the Front Left Corner
Total Occupants: 2
Describe Occupant Injuries: (Seating position/Were seat belts used/Air bag deployed?):
Seat belts were in use; airbags were not deployed; no injuries were sustained

HARDWARE

Impact Location (Check One): Cable Terminal section Other:
Describe Damage to Barrier:
Rate Overall Barrier Performance: Good

REPAIR

Number of posts damaged: 8 Was cable damaged?:
Did cable maintain tension? Yes

Cost to repair:

Labor	Material	Equipment	Total
\$724.72	\$755.17	\$243.36	\$1,723.25

Repair problems? (Difficulties in obtaining parts/repair guidance/or other):

Attach any supporting information, sketches, photos, accident reports, etc.

Evaluator: Tommy Arnold Date: September 11, 2006


Title: Transportation Engineer

Submit to Standards Engineer, Office of Roadway Engineering, Central Office, Thank you!


- Weekly inspection of crashes
- Completion of Evaluation forms
 - OH-1 crash data
 - Inspected damage
 - Repair costs
- Annual submittal of ISPE report to FHWA describing crash experience

Crash Trends

Total Crash Comparison




1-Mile Crash Rate Comparison



Crashes By Log Point

Frequency ADT






Crashes By Log Point

Frequency


Wire Rope Length within
2000' of Interchange

Crashes within 2000' of
Interchange



Collision Details

Crash Type




Collision Details


Crash Type

- At least 71% of the total crashes involved only 1 vehicle (not including Hit and Run crashes)
- Hit and Run crashes accounted for approx. 27% of total crashes per year

Contributing Circumstances




Collision Details Peak Hour




Vehicles Crossing the Ditch

- In other words, 28% of the wire rope crashes were backside hits




Environment Details

Road Condition




Environment Details

Light Condition



Crash Severity Details



■ Bottom Line: No cross-over fatal or incapacitating injuries

Other Details

- No trends related to the following:
 - Age
 - Alcohol use

Notable Crash Types

Notable Crashes

- Penetration
- Entanglement
- Vehicles exceeding design criteria

Penetration

- Approx. 4 per year
- No discernable trends



- Only 3 out of 13 were back-side hits

Two ropes did maintain contact with this vehicle

Entanglement



- Only 1 crash observed from July 2003 – June 2006



Vehicles Exceeding Design Criteria

- September 6, 2006 Semi-truck hit
- Other crashes included Mac truck, single unit truck, and Fire truck



Source: *The Enquirer*. Sept. 6, 2006

Resulting Damage

- Only 1 resulted in penetration

Wire Rope Damaged in Crash



Conclusion

Conclusion

- Cross-over crashes appear to be random events
 - Slightly higher percentage during dark conditions
 - Significantly higher percentage during wet conditions
 - Significantly higher percentage of crashes involved only 1 vehicle losing control

Conclusion

- From July 2001 to June 2003...
 - 17 fatal crashes (21 fatalities)
 - 9 cross-over fatal crashes (11 fatalities)

- From July 2003 to June 2006...
 - 4 fatal crashes (4 fatalities)
 - No cross-over fatal crashes

Questions?

Tommy Arnold, E.I.

ODOT-District 8

505 S SR741

Lebanon, OH 45036

513.933.6588

tom.arnold@dot.state.oh.us