



Caltrans First Repair Was A Half Collapse



Minor Damage to Plate - Two Shear Bolts Required



This Crew's First Repair Took 23 Minutes And They Were Happy To Get Off This Roadway So Fast



Transition Designs Are Available To Connect To Most Obstacles Or Shapes No Backup Support is Required