

Frontside Cable Breach Information

<i>Obs</i>	<i>Crash Date</i>	<i>County</i>	<i>Route</i>	<i>Location</i>	<i>Cable Offset From Ditch (Feet)</i>	<i>Median Width (Feet)</i>	<i>Approximate Distance To Barrier for Frontside Hit (Feet)</i>	<i>Impact Angle</i>	<i>Vehicle</i>
1	8/28/2002	Robeson	I-95	0.10 Miles North of MM 33 towards MM 34	2	35	15	20	2001 Ford Focus ZX3
2	1/25/2004	Duplin	I-40	At NC 41 (384.6 MM)	4	46	19	11	1996 Saturn SL
3	2/19/2004	Johnston	I-40	1.30 Miles West of NC 242 towards SR 1308	8	46	15	12	2004 Dodge Intrepid
4*	2/24/2004	Nash	US 64	0.8 Miles West of NC 231 towards SR 1137	4	68	30	26	2003 Toyota Corolla S
5	4/16/2004	Sampson	I-40	0.3 Miles East of SR 1845 (345 MM)	2	45	21	13	2000 Oldsmobile Alero
6	3/26/2004	Wake	I-40	0.60 Miles East of SR 1652 towards SR 1655	2	69	32	39	1997 Acura Integra
7	5/19/2004	Sampson	I-40	0.5 Miles East of SR 1711 (346.8 MM)	3	46	20	14	1995 Mitsubishi Montero LS
8	6/1/2004	Duplin	I-40	0.70 Miles West of SR 1102 towards SR 1141	4	47	19	20	2003 Honda Civic

*This crash occurred in test section where the cable orientation on the post is reversed (two cables on ditch side)

Backside Cable Breach Information

<i>Obs</i>	<i>Crash Date</i>	<i>County</i>	<i>Route</i>	<i>Location</i>	<i>Cable Offset From Ditch (Feet)</i>	<i>Median Width (Feet)</i>	<i>Approximate Distance To Barrier for Backside Hit (Feet)</i>	<i>Impact Angle</i>	<i>Vehicle</i>
1	11/13/2001	Durham	I-40	0.96 Miles East of SR 1110 towards NC 54	4	48	28	11	2000 Mercury Grand Marquis
2	2/19/2002	Johnston	I-40	0.19 Miles West of SR 1322 towards MM 320	7	49	31	27	2000 Daewoo Nubria SE
3	8/16/2002	Warren	I-85	0.50 Miles North of SR 1224 towards SR 1226	3	36	21	17	1993 Lincoln Town Car
4	4/3/2003	Edgecombe	US 64	0.91 Miles West of SR 1225 towards SR 1226	5	46	28	35	1991 Buick LeSabre Custom
5	10/17/2003	Sampson	I-40	300 Feet West of SR 1725	4	46	27	21	1995 Honda Civic EX Coupe
6	8/23/2003	Duplin	I-40	0.50 Miles West of SR 1141 towards SR 1918	5	46	28	12	1998 Volkswagon Jetta
7	9/1/2003	Duplin	I-40	0.60 Miles West of SR 1102 towards SR 1912	4	45	26	21	1995 Saturn SL
8*	1/9/2004	Nash	US 64	0.25 Miles East of SR 1306 towards SR 1911	4	68	38	28	1998 Ford Escort
9*	2/13/2004	Wake	US 64	0.50 Miles West of NC 39 towards US 264	3	67	37	28	1994 Oldsmobile Cutlass Ciera S
10	2/17/2004	Pender	I-40	2.30 Miles South of US 117 towards NC 53	3	45	25	30	1994 Honda Civic EX Coupe
11	6/5/2004	Robeson	I-95	0.80 Miles South of MM 27 towards MM 26	3	35	21	14	1998 Honda Civic CRX
12	6/6/2004	Johnston	I-40	0.70 Miles East of SR 1005 towards NC 96	7	45	29	23	1998 Acura 3.2 CL
13	6/9/2004	Cabarrus	I-85	0.60 Miles North of SR 1430 towards NC 73	6	69	41	26	1999 Chevrolet Camaro
14	6/26/2004	Johnston	I-40	0.15 Miles East of MM 332 towards MM 333	4	45	27	22	1994 Oldsmobile Eighty Eight
15	11/19/2004	Warren	I-85	0.15 Miles North of SR 1237 towards SR 1224	4	36	22	5	2003 Oldsmobile Alero

*This crash occurred in test section where the cable orientation on the post is reversed (two cables on ditch side)